

# SCADAPack Workbench Release Notes

## SCADAPack Workbench 6.6.10 Release Notes

---

### Application Version

The SCADAPack Workbench application version is 6.6.10.

### Firmware Versions

- The latest SCADAPack firmware at the time of release is:
  - 1.77 for SCADAPack 314, SCADAPack 330, SCADAPack 334, SCADAPack 350, and SCADAPack 357 controllers
  - 1.77 for SCADAPack 4203 controllers
  - 2.25 for SCADAPack 32 and SCADAPack 32P controllers
  - 2.50 for SCADAPack 100 controllers
- The latest SCADAPack E firmware at the time of release is 8.20.1 for SCADAPack E Remote Terminal Units (RTUs).

### New Features (6.6.10)

There are no new features in this release.

### Enhanced Features (6.6.10)

- WI 61734: Updated the About dialog for the Schneider Electric email address, technical support information, and also updated Cybersecurity topic links
- WI 61776: Removed applications for discontinued TransNet, Freewave, and MaxStream radios and SCADAPack SDI-12 driver from the SCADAPack IEC 61131-3 Workbench and Utilities CD
- WI 65226: Updated the Check a Product link
- WI 68121: Updated the Technical Support address

### Functional Changes (6.6.10)

There are no functional changes for SCADAPack Workbench version 6.6.10.

### Fixed Issues (6.6.10)

- WI 60889: Addressed SCADAPack Workbench vulnerabilities CVE-2020-27271 and CVE-2020-27273
- WI 65055: Addressed SCADAPack Workbench vulnerability CVE-2022-0221
- WI 65057: Addressed SCADAPack Workbench vulnerability CVE-2022-0221
- WI 65134: Corrected a Visual Studio 2013 Isolated Shell installation issue and renamed the VS2013 Isolated Shell on the DVD and the docs to the following:
  - vs\_isoshell.exe
  - VS12-KB3107629.exe
- WI 67050: Addressed SCADAPack Workbench vulnerabilities CVE-2022-2463, CVE-2022-2464, CVE-2022-2465

## Known Issues (6.6.10)

- WI 64022: Workbench will sometimes require that a program be rebuilt and redownloaded, even if it hasn't changed, prior to entering debug mode.

## SCADAPack Workbench 6.6.8a Release Notes

---

### Application Version

The SCADAPack Workbench application version is 6.6.8a.

### Firmware Versions

- The latest SCADAPack firmware at the time of release is:
  - 1.77 for SCADAPack 314, SCADAPack 330, SCADAPack 334, SCADAPack 350, and SCADAPack 357 controllers
  - 1.77 for SCADAPack 4203 controllers
  - 2.24 for SCADAPack 32 and SCADAPack 32P controllers
  - 2.50 for SCADAPack 100 controllers
- The latest SCADAPack E firmware at the time of release is 8.17.1 for SCADAPack E Remote Terminal Units (RTUs).

### New Features (6.6.8a)

- There are no new features in this release.

### Enhanced Features (6.6.8a)

- SCADAPack Workbench 6.6.8a is automatically licensed. It is not necessary to obtain a new license after upgrading. See the user manual for details.

### Functional Changes (6.6.8a)

SCADAPack Workbench version 6.6.8a provides the following functional changes.

- WI 61776: Obsolete applications for TransNet, Freewave, and MaxStream radios are removed from the installation program. The discontinued SCADAPack SDI-12 Driver is removed from the installation program.

### Fixed Issues (6.6.8a)

- WI 61831: The Help Viewer in 6.6.8 opened a PDF version of the help. This is corrected in 6.6.8a. The PDF version of the file is removed, and the normal help viewer functions as designed.

# SCADAPack Workbench 6.6.8 Release Notes

---

## Read Before Installation

A new license is required after installation of SCADAPack Workbench 6.6.8. Allow time to obtain a new license when planning your installation.

When installing SCADAPack Workbench 6.6.8 on a computer that was running a previously licensed version, a message states that the free version is running. This means you need to activate the SCADAPack Workbench 6.6.8 license. To obtain new license registration keys, contact Schneider Electric customer support at [ordersTRSS@se.com](mailto:ordersTRSS@se.com).

## Application Version

The SCADAPack Workbench application version is 6.6.8.

## Firmware Versions

- The latest SCADAPack firmware at the time of release is:
  - 1.77 for SCADAPack 314, SCADAPack 330, SCADAPack 334, SCADAPack 350, and SCADAPack 357 controllers
  - 1.77 for SCADAPack 4203 controllers
  - 2.24 for SCADAPack 32 and SCADAPack 32P controllers
  - 2.50 for SCADAPack 100 controllers
- The latest SCADAPack E firmware at the time of release is 8.17.1 for SCADAPack E Remote Terminal Units (RTUs).

## New Features (6.6.8)

- There are no new features in this release.

## Enhanced Features (6.6.8)

- The ISaGRAF Gateway OPC® Data Access Server version 6.6 with load on demand enables monitoring applications running on controllers with either big-endian or little-endian format for communication with an ISaGRAF version 5 target.
- Import or export variables in Excel Workbook .xlsx format. This format supports up to 1,048,576 by 16,384 rows and columns.

## Technical Notes (6.6.8)

- When performing searches from the Solution Explorer to locate specific items within the tree structure, searches are case-insensitive for lowercase text in the search field. However, searches become case-sensitive upon entering uppercase text in the field. Microsoft states this behavior is as designed: <https://connect.microsoft.com/VisualStudio/feedback/details/1078288/solution-explorer-search-filter-is-case-sensitive-it-should-be-case-insensitive>
- When SCADAPack Workbench displays a message that the ACP has encountered a problem, please take the time to generate a report to help us improve the quality of our product. When generating a report, you can choose to capture and attach a screenshot. Upon generation, a dialog box indicates

the location and name of the report where you can choose to send the file to our technical support team at [supportTRSS@se.com](mailto:supportTRSS@se.com). For such problems, make sure to close SCADAPack Workbench without saving changes to your project and restart the software to avoid corrupting files.

## Functional Changes (6.6.8)

SCADAPack Workbench version 6.6.8 provides the following functional changes.

- User Story 39895: (ISE6-1291) The Start menu organization is updated to work better with Windows 10.

## CAM 3 and CAM 5

- The Debug menu no longer displays the Parallel Stacks and Parallel Watch commands while the project is in simulation mode.
- Complex inputs of a user-defined function display N/A in the LD language editor. Previously, complex inputs of a user-defined function displayed the value OFFLINE.
- Entering a comment with more than 60 characters for an I/O channel displays the message *The maximum length for this field is 60 characters*. SCADAPack Workbench prevents saving comments for an I/O channel with more than 60 characters. Previously, SCADAPack Workbench accepted comments with more than 60 characters for an I/O channel. When building the project, a comment with more than 60 characters caused a build error.
- In the SFC editor, adding an LD transition creates a level 2 LD language container with a rung and a coil. The LD transition sets the following restrictions:
  - The coil cannot be deleted.
  - The coil cannot be assigned a variable.
  - A new rung cannot be added.

ISaGRAF version 6.6.3 allows deleting empty coils and prevents assignment of variables to empty coils.

## CAM 3

- The boolean variable values **MsgTrue** and **MsgFalse** are not supported. These variables values were supported in ISaGRAF version 3.x.x. Remove any **MsgTrue** and **MsgFalse** values before importing an ISaGRAF version 3.x.x project.
- Right-clicking a POU in **Solution Explorer** does not display **Clean**. In ISaGRAF version 6.3, right-clicking a POU in **Solution Explorer** and then selecting **Clean** cleans the project.
- This release does not support ISaGRAF 3 resource (\*.rsc) files.

## Fixed Issues (6.6.8)

- WI 57547: SCADAPack Workbench reported “too many I/O variables” under Windows 10 but compiles successfully on Windows 7. This is fixed.

- WI 40003: (ISE6-1165) There is no warning with the Modbus Master Polling function blocks when both Start\_reg\_5digit and Start\_reg\_6digit parameters are configured. This is by design, but was not documented. The behaviour has been documented.
- WI 39888: (ISE6-1299) SCADAPack Workbench Quick Start Guide was available twice under the Windows 10 and 8 Start Menu. This is fixed.
- WI 39889: (ISE6-1298) SCADAPack Workbench could not build a CAM3 project on Windows 10 on some workstations. This is fixed.
- WI 56699: An Online change displayed an error message when building for a SCADAPack 334E on some workstations. This is fixed.
- WI 40027: (ISE6-1140) The Comparison (=) Function block gave incorrect result when one input was manually set, and the other input came from the output of a function block. This is corrected.

### CAM 3 and CAM 5

- This release corrects the issues described in Rockwell Automation Product Safety Advisory (PSA) 2019-08-002.
- In the FBD or LD editor, variables with names that include an underscore immediately followed by a digit such as \_1, \_2, \_1\_1\_1 do not display the power flow coloring, data type, and online value for the variable. [Rockwell TFS 35187]  
In this release, in the FBD or LD editor, variables with names that include an underscore immediately followed by a digit such as \_1, \_2, \_1\_1\_1 display the power flow coloring, data type, and online value for the variable.
- ISaGRAF does not support adding a second device from the ISaFREE template in the Deployment view. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 52386]  
In this release, ISaGRAF supports adding a second device from the ISaFREE template in the Deployment view.
- When debugging an FBD POU, the input value of a function displays an incorrect value. [Rockwell TFS 58980]  
In this release, when debugging an FBD POU, the input value of a function does not appear.
- When downloading a device using a serial port when no serial port is found on the computer, an error message appears. [Rockwell TFS 51673]  
In this release, when downloading a device using a serial port when no serial port is found on the computer, the Output window displays an error.
- Deleting a group of variables that are sorted by name from the dictionary and then undoing the deletion may select the current row as well as undeleted rows. [Rockwell TFS 40993]  
In this release, deleting a group of variables that are sorted by name from the dictionary and then undoing the deletion selects only the current row.
- The Online Change toolbar icon and shortcut menu do not appear in the Japanese version of the Automation Collaborative Platform. [Rockwell TFS 41347]  
In this release, the Online Change toolbar icon and shortcut menu appear in the Japanese version of the Automation Collaborative Platform.
- Importing a .tdb file that has an added, modified, or deleted Network Resource Binding parameter displays the error message "Unhandled exception occurred during the filling of the

table Instance of ResNetPara". The project does not update. Closing the error message closes the project and the project cannot re-open. [Rockwell TFS 51033]

In this release, importing the .tdb file that has an added, modified, or deleted Network Resource Binding parameter updates the project.

- The I/O Device view of a resource does not open after creating an I/O device instance that has 2000 channels and then closing and re-opening the project. The Output window displays the message "Exception of type 'System.OutOfMemoryException' was thrown" and an error message appears. [Rockwell TFS 37000]

In this release, the I/O Device view of a resource opens after creating an I/O device instance that has 2000 channels and then closing and re-opening the project.

- Importing an ISaGRAF version 5.22 project and library replaces manual instances of function blocks with automatic instances. [Rockwell TFS 52260]

In this release, importing an ISaGRAF version 5.22 project and library retains manual instances of function blocks.

- Deleting a derived type variable that is monitored in the Spy List and then debugging the application displays an error message. [Rockwell TFS 62556]

In this release, deleting a derived type variable that is monitored in the Spy List and then debugging the application displays an Invalid icon for the deleted variable in the Spy List.

- In Document Overview, zooming in on a link between two variables does not display the selected area and displays an error message. [Rockwell TFS 48833]
- In this release, zooming in on a link between two variables displays the selected area.
- Attempting to display the properties of a resource in Device view displays an error message. [Rockwell TFS 42818]
- In this release, the properties of a resource appear in Device view.

- If the Project location or POU name includes Chinese characters, building a solution that has a POU fails and the Output window displays an error. [Rockwell TFS 61819]

In this release, if the Project location or POU name includes Chinese characters, the Chinese characters do not cause an error when building.

- Importing an exchange file displays an error message if the imported resource name and the program name are the same. [Rockwell TFS 51117]
- In this release, the error message "Unable to import the file; the file may be corrupted or in an invalid format" appears if the imported resource name and the program name are the same.
- When using automatic instances of function blocks, the values of function block outputs do not appear in debug mode. [Rockwell TFS 41162]
- In this release, when using automatic instances of function blocks, the values of function block outputs appear in debug mode.
- Copying and pasting a POU body that contains library function blocks from one FBD program to another does not paste the correct data types for instances of function blocks. [Rockwell TFS 58991]
- In this release, copying and pasting a POU body that contains library function blocks from one FBD program to another pastes the correct data types for instances of function blocks.

- The Spanish version of the ISaGRAF opens the English version of the Automation Collaborative Platform when selecting Start > All Programs > ISaGRAF x.x > Automation Collaborative Platform x.x. [Rockwell TFS 27157]
- In this release, the Spanish version of ISaGRAF opens the Spanish version of the Automation Collaborative Platform when selecting Start > All Programs > ISaGRAF x.x > Automation Collaborative Platform x.x.
- After editing an ST POU body, the Cross Reference Browser incorrectly displays an icon indicating that the cross reference data is up-to-date. [Rockwell TFS 26173]  
In this release, after editing an ST POU body, the Cross Reference Browser displays a warning icon indicating that the cross reference data is out of date.
- Building a project that has an FBD POU body that contains an unconnected vertical bar, left power rail, or right power rail displays an error message. [Rockwell TFS 27484]  
In this release, building a project that has an FBD POU body that contains an unconnected vertical bar, left power rail, or right power rail displays the applicable message in the Output window. Double-clicking the message in the Output window displays the language editor with the unconnected component selected.
- Deleting branches from a rung in the LD POU editor takes excessive time. [Rockwell TFS 40867]  
In this release, deleting branches from a rung in the LD POU editor takes a similar duration as in ISaGRAF version 6.2.
- Scrolling the language editor while debugging an ST program causes the yellow arrow that indicates a breakpoint to disappear. [Rockwell TFS 57317]  
In this release, scrolling the language editor while debugging an ST program does not cause the yellow arrow that indicates a breakpoint to disappear.
- Undoing changes made to the FBD POU in the language editor does not revert the last change and misplaces elements and connections lines. [Rockwell TFS 50464]  
In this release, undoing changes made to the FBD POU in the language editor reverts the last change and the placement of elements and connection lines.
- Naming a project with unsupported characters opens the Enter Password dialog box. [Rockwell TFS 52321]  
In this release, naming a project with unsupported characters opens an error message.
- Copying and pasting 15 or more rungs in a ladder diagram takes excessive time. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 48250]  
In this release, copying and pasting 15 or more rungs in a ladder diagram takes a similar duration as in ISaGRAF version 6.4.1.
- Renaming bit access or array member variables in the dictionary does not display a yellow warning symbol for elements with errors in the LD language editor. [Rockwell TFS 55974]  
In this release, renaming bit access or array member variables in the dictionary displays a yellow warning symbol for elements with errors in the LD language editor.
- Changing the data type of an instance of a function block in the dictionary does not update the name of the function block in the LD language editor. [Rockwell TFS 55990]

In this release, changing the data type of an instance of a function block in the dictionary updates the name of the function block in the LD language editor.

- The ISaGRAF compiler may generate errors when a function block that does not have inputs serves as the input for multiple function blocks in an incorrect FBD POU execution order. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 30643]

In this release, to help prevent errors, the ISaGRAF compiler processes the function block serving as the input for the multiple function blocks before processing other function blocks.

- Opening an LD POU takes excessive time. [Rockwell TFS 48276, TFS 48088]

In this release, opening an LD POU takes a similar duration as in ISaGRAF version 6.4.

- A project builds even when the array or structure size exceeds the 2 GB limit. [Rockwell TFS 48330]

In this release, when the array or structure size exceeds the 2 GB limit, the project build fails and a compilation error appears.

- Using an exchange file to import a POU takes excessive time when a POU body is open. [Rockwell TFS 49981]

In this release, the time it takes to use an exchange file to import a POU when the POU body is open is reduced.

- The CAM 3 compiler generates power flow debugging information for a POU even if the Generate Debug Info property is set to False. [Rockwell TFS 40756]

In this release, the CAM 3 compiler does not generate power flow debugging information if the Generate Debug Info property is set to False.

- In some localized versions of the Automation Collaborative Platform, the Error List incorrectly displays warnings as errors. [Rockwell TFS 44515]

In this release, the Error List in localized versions of the Automation Collaborative Platform displays generated warnings as warnings.

- Adding a variable to the Spy List displays variable values as OFFLINE. Displaying values for added variables in the Spy List required closing and reopening the Spy List. [Rockwell TFS 46489]

In this release, adding a variable to the Spy List displays the values without having to close and reopen the Spy List.

- Importing an ISaGRAF version 5 project fails to download code to the target. Ladder Diagram Optimized Code in Target Features displays an incorrect value. [Rockwell TFS 60208]

In this release, importing an ISaGRAF version 5 project downloads code to the target. Ladder Diagram Optimized Code in Target Features displays the correct value based on the FeatureOptCode value in the .mdb file for the imported project:

- True: FeatureOptCode = Yes
- False: FeatureOptCode = No
- False: FeatureOptCode has no value

- After adding an I/O device, opening an I/O parameter changes the default float parameter value from 0 to 0.0 in the I/O Parameter dialog box. Reopening the I/O parameter and clicking OK in the I/O Parameter dialog box displays the error message “The value is either too large of too small for [parameter]”. [Rockwell TFS 57584]



In this release, opening an I/O parameter does not change the default float parameter value from 0 to 0.0 in the I/O Parameter dialog box. The I/O Parameter dialog box accepts any 0 float values such as 0 and 0.0.

- Deleting an array used in a structure prevents creating elements in the structure. [Rockwell TFS 42629]

In this release, deleting an array used in a structure does not prevent creating elements in the structure.

- Changing the Logical Value for a variable in the dictionary displays the value WAIT. [Rockwell TFS 43629]

In this release, changing the Logical Value for a variable in the dictionary displays the entered value.

- Adding a variable to the Spy List displays variable values as OFFLINE. Displaying values for added variables in the Spy List requires closing and reopening the Spy List. [Rockwell TFS 46489, TFS 43838]

In this release, adding a variable to the Spy List displays the values without having to close and reopen the Spy List.

- Debugging or simulating a project consumes excessive memory when an ST POU references variables. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 52572]

In this release, memory consumption is stable while debugging or simulating a project that contains an open ST POU that references variables.

- The FBD compiler does not create a MEMO variable for each instance of a P/N contact. This behavior is inconsistent with the LD compiler behavior and may lead to unexpected build results. [Rockwell TFS 43995]

In this release, the FBD and LD compilers create a MEMO variable for each instance of a P/N contact by default.

- The DisableNewLDMemoContacts parameter value in the Diamond.ini file determines the behavior of P/N contacts:

- 0 = create a MEMO variable for each instance of a P/N contact
- 1 = create only one MEMO variable for all the instances of a P/N contact

- Copying a rung that has a ladder and a user-defined function block and then pasting the rung to another ladder displays hidden parameters in the LD language editor. [Rockwell TFS 50797]

In this release, pasting the copied rung no longer displays hidden parameters.

## CAM 5

- The SCADAPack Workbench exits without saving when double-clicking an I/O device instance in a project imported from an exchange file. [Rockwell TFS 66429]
- LD POUs containing backward jumps may execute the application in an infinite loop. [Rockwell TFS 66506]
- FBD POUs containing backward jumps may execute the application in an infinite loop [Rockwell TFS 66605]

- For FBD POU bodies, incorrectly closing comments causes unexpected compiler errors. [Rockwell TFS 48610]  
In this release, no compiler errors appear.
- When simulating a project that has a dependency on a library, error symbols for “Undefined POU” appear in the language editor even if the location of the library is defined. [Rockwell TFS 39620]  
In this release, when simulating a project that has a dependency on a library, error symbols for “Undefined POU” do not appear in the language editor if the location of the library is defined.
- Closing a project takes excessive time compared to ISaGRAF version 6.4.1. [Rockwell TFS 61521]  
In this release, the length of time to close a project is reduced.
- When importing a POU from a password-protected resource, an error message appears. [Rockwell TFS 62564]  
In this release, importing a POU from a password-protected resource prompts the user to enter the password.
- The function block instance input displays incorrect values in the POU body when **Flexible Array and FB Parameters by Reference** in **Target Features** is set to **True**. [Rockwell TFS 55076]  
In this release, the function block instance input displays correct values in the POU body when **Flexible Array and FB Parameters by Reference** in **Target Features** is set to **True**.
- Importing a project created from a previous software version that has password-protected POUs prompts the user to enter a password for each POU. [Rockwell TFS 50528]  
In this release, importing the project from a previous software version that has password-protected POUs does not prompt the user to enter a password for each POU. Opening the POU in the language editor prompts the user to enter a password.
- Deleting an embedded user-defined function block (UDFB) displays the message “Cannot convert a complex type to a single type” in the Output window and displays an error message. This anomaly occurs when retaining local variables for the instance of the embedded UDFB. [Rockwell TFS 56288]  
In this release, deleting the embedded UDFB removes the UDFB and the instance of the embedded UDFB becomes undefined.
- Opening I/O Device view and changing the I/O device selection takes excessive time for a large wired array such as [1...2000]. [Rockwell TFS 62580]  
In this release, the I/O Device view opens in less than 30 seconds and changing the I/O device selection is faster.
- The Automation Collaborative Platform does not import a resource that has a duplicate producing group ID in the project. An error message appears. [Rockwell TFS 38447]  
In this release, the Automation Collaborative platform supports importing a resource that has a duplicate producing group ID in the project. Entering an ID value in the Properties window for a producing group in a binding displays the message "Property value is not valid" if another producing group with the same ID exists in the resource.
- Making changes to Global Variables before performing an online change does not rebuild the project and displays incorrect variable values. [Rockwell TFS 57212]

- In this release, making changes to Global Variables before performing an online change rebuilds the project and displays correct variable values.
- Changing the size of the dimension of an Array data type that a Structure data type uses displays an error message. Selecting the Structures tab in Data Types closes the Automation Collaborative Platform. [Rockwell TFS 60911]
- In this release, changing the size of the dimension of an Array data type that a Structure data type uses applies the size change.
- Selecting Tools > Execution Order does not display the execution order of a function block diagram in the language editor if the POU body contains an unconnected block. [Rockwell TFS 49518]  
In this release, selecting Tools > Execution Order displays the execution order of a function block diagram in the language editor even if the POU body contains an unconnected block.
- Renaming a POU in a project that uses bindings and then building the project changes the configuration of the bindings of local variables. The Error List indicates that a variable in the binding is not found. [Rockwell TFS 55721]  
In this release, renaming a POU in a project that uses bindings and then building the project does not change the configuration of the bindings of local variables.
- Incremental builds omit child SFC POUs with changes to global variables or data types. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 58701, TFS 50731]  
In this release, incremental builds include SFC children with changes to global variables or data types. The number of child SFC POUs may affect build time.
- Copying and pasting program POUs or variables takes excessive time. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 50931]  
In this release, copying and pasting POUs or variables takes a similar duration as in ISaGRAF version 6.4.1.
- Adding a POU online and then restarting the resource does not start an SFC program. [Rockwell TFS 44361]  
In this release, adding a POU online and then restarting the resource starts the SFC program.
- Yes to All and No to All buttons do not appear when prompted to stop downloading a resource from a previously downloaded project that has multiple resources. [Rockwell TFS 40796]  
In this release, the Yes to All and No to All buttons appear in the dialog box when prompted to stop downloading a resource from a previously downloaded project that has multiple resources.
- The ISaGRAF compiler generates unrecognized 1 GAIN LD optimization TIC codes on the ISaGRAF version 5.22 target. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 36948]  
In this release, the ISaGRAF compiler does not generate unrecognized TIC codes on the ISaGRAF version 5.22 target.
- Opening the Variable Selector takes excessive time. [Rockwell TFS 50229, TFS 51253]  
In this release, opening the Variable Selector takes a similar duration as in ISaGRAF version 6.4.
- When attempting to view the cross reference for a password-protected variable, selecting Cancel on the Enter Password dialog box causes SCADAPack Workbench to stop responding. [Rockwell TFS 51364]

In this release, when attempting to view the cross reference for a password-protected variable, selecting Cancel closes the Enter Password dialog box.

- The ISaGRAF compiler miscalculates OEM parameter offsets for simple and complex I/O devices in the resource configuration file. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 47551]

In this release, the compiler correctly calculates the OEM parameter offsets for simple and complex I/O devices in the resource configuration file.

- Building and then debugging an imported project does not retain all Retained variables for non-enhanced targets. [Rockwell TFS 41358]

In this release, building and then debugging an imported project retains all Retained variables for non-enhanced targets. Retaining sub-variables or instances of function blocks for non-enhanced targets displays a compilation error when building and then debugging the project.

- The dictionary displays an incorrect selection in the Retained column for variables of an imported device or POU. [Rockwell TFS 51722]

In this release, the dictionary displays correct values in the Retained column for variables of an imported device or POU based on the IsRetained value in the exchange file:

- selected: IsRetained = true for all variable subfields
- cleared: IsRetained = false for all variable subfields
- shaded: IsRetained = true for some variable subfields, IsRetained = false for some variable subfields

- Connection to multiple controllers fails if one of the controllers is not running. [Rockwell TFS 51688]

In this release, connection to multiple controllers does not fail if one of the controllers is not running.

- When stopping debugging of an online project that has SFC and other programming language breakpoints, changing a resource from stepping mode to run mode when prompted stops the resource from running. The Diagnostic tool displays the Resource Mode value Break. [Rockwell TFS 35050]

In this release, when stopping debugging of an online project that has SFC and other programming language breakpoints, changing a resource from stepping mode to run mode when prompted does not stop the resource from running. The Diagnostic tool displays the Resource Mode value RealTime.

- In debug mode, locking an element of a structure variable in the dictionary or Spy List when the Locked Variables window is open displays an error message and does not lock the element. [Rockwell TFS 50985]

In this release, locking an element of a structure variable in the dictionary or Spy List when the Locked Variables window is open locks the element.

- Adding a structure or array data type to the library and then building the project without saving the library displays an error message. [Rockwell TFS 38984]

In this release, adding a structure or array data type to the library and then building the project without saving the library does not display an error message.

- Building a project that contains a STRING array as a function input parameter causes a build error with address overlaps. [Rockwell TFS 49373]  
In this release, building a project that contains a STRING array as a function input parameter does not cause a build error with address overlaps.
- Changing the index of a complex I/O device instance in a project may result to a build error. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 50078]  
In this release, changing the index of a complex I/O device instance in a project does not cause a build error.

### CAM 3

- Cannot lock an I/O variable with an offset is greater than 4096. The lock request is executed on the incorrect variable. [Rockwell TFS 59076]  
In this release, the lock request executes on the correct I/O variable when the offset is greater than 4096.
- The Network Connection property Stop Bits incorrectly displays the options None, One, Two, and OnePointFive. [Rockwell TFS 51674]  
In this release, the values are listed in numerical order and display correctly as 0, 1, 1.5, and 2.
- Renaming an ISaVIEW screen removes programs, functions, and function blocks from the project. [Rockwell TFS 62853]  
In this release, renaming an ISaVIEW screen does not remove programs, functions, and function blocks from the project.
- The message “Would you like to build?” appears when restarting the simulation of an application that is saved and built without error, even if there are no changes to the application. This anomaly occurs if the POU body contains a function block instance and Generate Debug Info is set to True in the Properties window for the Function Block Diagram (FBD) or Ladder Diagram (LD) POU. [Rockwell TFS 62187]  
In this release, the message “Would you like to build?” does not appear when restarting the simulation of an application that is saved and built without error.
- Assigning a conversion function or table to an I/O variable in the I/O Wiring tool does not display the assigned function after saving and re-opening the project. [Rockwell TFS 39456]
- In this release, assigning a conversion function or table to an I/O variable in the I/O Wiring tool displays the assigned function after saving and re-opening the project.
- Changing the data type of a local variable of a function block and then building and simulating the application does not display updated variable values when opening the dictionary. An error message appears. [Rockwell TFS 59613]
- In this release, changing the data type of a local variable of a function block and then building and simulating the application displays updated variable values when opening the dictionary.
- In the Cross Reference Browser, right-clicking a block in the References pane and selecting Go to Reference does not display the POU language editor for the block. [Rockwell TFS 46171]
- In this release, right-clicking a block in the References pane and selecting Go to Reference displays the POU language editor for the block.

- Entering a negative value in Cycle Timing (ms) for a device displays an error message. [Rockwell TFS 26128]
- In this release, entering a negative value in Cycle Timing (ms) does not change the value Cycle Timing (ms).
- The Generate Documentation output file does not display OEM parameters of I/O devices. [Rockwell TFS 59481]
- In this release, the Generate Documentation output file displays OEM parameters of I/O devices.
- When using a Windows 10 operating system, a project does not build if the project has an LD POU that uses a defined word. An error message appears. [Rockwell TFS 54929]
- In this release, when using a Windows 10 operating system, having an LD POU that uses a defined word in the project does not cause an error when building.
- Cleaning a project incorrectly deletes all files with a file extension that begins with x, for example .xml and .xls, and resets the application number to 1. [Rockwell TFS 59078]  
In this release, cleaning a project only deletes the intermediate and output files generated during the last build operation.
- Renaming the target device empties library POU bodies, which causes the project build to fail. [Rockwell TFS 59519]  
In this release, renaming the target device does not modify POU's in the library.
- The Error List for build errors displays the file extension without the POU file name in the File column. [Rockwell TFS 43790]  
In this release, the Error List for build errors displays the POU file name with the file extension in the File column.
- When debugging an LD program, the language editor may not display the correct line color for monitoring the function block output. [Rockwell TFS 47955]  
In this release, the language editor displays the correct line color for monitoring function block outputs:
  - black – the output value is unavailable
  - red – the output value is true
  - blue – the output value is false
- For FBD, LD, and ST programs, double-clicking an error in the Error List does not highlight the variable shape that has an error in the language editor. [Rockwell TFS 55053]  
In this release, double-clicking an error in the Error List highlights the variable shape that has an error in the language editor.
- The language editor is editable while in debug mode when the application cannot connect to the target. [Rockwell TFS 43579]  
In this release, the language editor is read-only while in debug mode when the application cannot connect to the target.
- If a variable has a comment with more than 60 characters, building a project displays an error message. [Rockwell TFS 45819]  
In this release, entering a comment to a variable displays a warning if the comment exceeds 60 characters and does not save the comment. Importing an .xls file that contains a variable

comment with more than 60 characters imports the variable but clears the comment from the variable.

- If the I/O Wiring tool is open, downloading or simulating a project fails. [Rockwell TFS 38242]  
In this release, if the I/O Wiring tool is open, it does not cause the download or simulation of a project to fail.
- Selecting Unlock in the Locked Variables viewer does not unlock the selected variables. [Rockwell TFS 38140]  
In this release, selecting Unlock in the Locked Variables viewer unlocks the selected variables.
- Importing variables using an .xls file does not import I/O wirings of complex devices. [Rockwell TFS 45834]  
In this release, importing variables by using an .xls file imports I/O wirings if the I/O device supports I/O wiring. A warning appears if there are invalid I/O wirings in the imported .xls file.
- Importing an ISaGRAF 3 project takes excessive time. [Rockwell TFS 46940]  
In this release, importing an ISaGRAF 3 project takes a similar duration as in ISaGRAF version 6.4.
- Building and then simulating a project that has nested in-line function blocks displays an incorrect POU build order. [Rockwell TFS 60920]  
In this release, building and then simulating a project that has nested in-line function blocks displays the correct POU build order.
- When building a project or library that has two local function block instances in two ST programs that have the same name, the compiler recognizes a function block instance as global instead of local. [Rockwell TFS 59634]  
In this release, when building a project or library that has two local function block instances in two ST programs that have the same name, the error “[FB instance]: name already used for another object [FB instance]” appears in the Output window and error message.
- After changing the order of an I/O board instance in the I/O Wiring tool and then building the application, downloading the application to the target displays an error message. [Rockwell TFS 59119]  
In this release, changing the order of an I/O board instance in the I/O Wiring tool and then building the application does not cause the download of the application to the target to fail.
- Renaming a wired variable that is used by a POU and then building the application does not rebuild the POUs. Downloading the application to the controller displays an error in the controller. [Rockwell TFS 58662]  
In this release, to help prevent downloading errors, renaming a wired variable and then building the application without updating the POUs generates a build error.
- Downloading a project takes excessive time. [Rockwell TFS 46462]  
In this release, downloading a project takes a similar duration as in ISaGRAF version 3.
- Building an imported project that has a file with a file name of more than 20 characters displays an error message. [Rockwell TFS 46516]  
In this release, building an imported project that has a file with a file name of more than 20 characters does not display an error message.

- When debugging an LD or FBD program, the language editor may not display the correct line color for monitoring the function block output. [Rockwell TFS 47955, TFS 58350, TFS 40915]  
In this release, when debugging an LD or FBD program, the language editor displays the correct line color for monitoring function block outputs:
  - black – the output value is unavailable
  - red – the output value is true
  - blue – the output value is false
- Changing the initial value of a variable of an FBD program and then downloading the application to the controller retains the original initial value. [Rockwell TFS 43715]  
In this release, changing the initial value of a variable of an FBD program project and then downloading the application to the controller resets the initial value to 0.
- If a project contains more than 4096 boolean variables or more than 4096 analog variables, forcing the value of a locked output variable may not change the physical value. Forcing the value of a locked input variable may incorrectly change the physical value. [Rockwell TFS 61795]  
In this release, forcing the value of a locked output variable modifies the physical value. Forcing the value of a locked input variable does not change the physical input value and modifies the logical value.

## Known Issues (6.6.8)

### CAM 3 and CAM 5

- When canceling the import of an exchange file, ISaGRAF displays an incorrect message while the cancelation is successful. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 24329]  
There is no workaround.
- The Dictionary displays the incorrect lock status of variable members. Anomaly first identified in ISaGRAF version 6.3.2. [Rockwell TFS 41362]  
To work around this issue, view the correct lock status for variable members in the Locked Variables viewer.
- When resetting the toolbox for FBD, LD, SFC, or ST programming languages, the icons for some or all elements may not display correctly. Anomaly first identified in ISaGRAF version 6.4.1. [Rockwell TFS 26106]  
To work around this issue, close and reopen ISaGRAF.
- In the Customize dialog box for menu bar, toolbar, and context menu items, applying the Reset All command may cause an unexpected behavior. Anomaly first identified in ISaGRAF version 6.4.1. [Rockwell TFS 27178]  
To work around this issue, remove the effects from having applied the Reset All command, reset all environment settings to the default by selecting Import and Export Settings > Reset all settings from the Tools menu.
- When generating documentation for projects, devices, and programs from the Generate Document window, the generated document does not contain the functions and function blocks of a library. [Rockwell TFS 44178]  
To generate documentation for functions and function blocks of a library, copy the functions



and function blocks of a library to a new project, and then generate documentation from the new project.

- Inserting a block from the Block Library to a function block in the FBD editor displays the Enter Password dialog if the function block is used in a password-protected program. Selecting Cancel inserts the block without the variable instance for the function block. [Rockwell TFS 55926]
- The find and replace feature only enables using the Find Next and Replace commands with the Current Document option for POUs. [Rockwell TFS 25826]  
Perform searches and replacements for a selected POU body by pressing Ctrl+F, then setting the Look In field to Current Document and using only the Find Next or Replace commands.
- When a project has two targets that contain the same C function blocks, changing the target displays an error when building the project. The reference data types appear undefined. [Rockwell TFS 39238]  
Correct the data types manually.

To work around this issue:

1. Export the project.
  2. Create a new simulator project.
  3. Import the target definition in the new project.
  4. Change the target type of the device.
  5. Import the resource under the device.
  6. Copy and paste define words from the original project to the new project.
- Modifying the structure of a function block causes SCADAPack Workbench to stop responding. This anomaly occurs when an associated variable with a retained value already exists in a dictionary. [Rockwell TFS 52495]  
There is no work around.
  - The cycle overflow warning is not informative. The parameter is always 0. The resource that caused the overflow is not identified. [Rockwell TFS 44697]  
There is no work around.
  - The Cross Reference Browser does not display variable references located in SFC transitions. This behavior is inconsistent with the Cross Reference Browser behavior in ISaGRAF version 6.4. [Rockwell TFS 50453]  
There is no work around.
  - Simulation of a project does not start if the project folder name has a hyphen, for example, Project1 - Copy. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 61901]  
To work around this issue, remove hyphens from the project folder name before simulating the project.
  - Selecting the Show Topic in Contents button in Microsoft Help Viewer does not display the selected topic in the Contents tab. Anomaly first identified in ISaGRAF version 6.6.7. [Rockwell TFS 65597]  
To work around this issue, when performing a search in Search tab, click the search result twice and then click the Show Topic in Contents button.

- The Cross Reference Browser may not list all variables, blocks, and defined words as used in a project if an operator and a literal value in an ST statement do not have a space in between, for example, `myInt := 1 +2`. [Rockwell TFS 60722]  
To work around this issue, use a space between the operator and literal value in ST statements, for example, `myInt := 1 + 2`.

## CAM 5

- After importing a project from an exchange file, additional I/O devices appear in Device Selector. Adding these I/O devices causes unexpected results in the application. [Rockwell TFS 67052]  
To avoid this issue, create a project by using the required project template, and then import each device from the exchange file.
- When importing variables, no validation occurs to check that wiring definitions correspond to array dimensions or structure data types. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 34230]  
To work around this issue, before importing wired array or structure variables, make sure that the number of wirings corresponds to the number of members of those variables.
- When changing a dependency path for a library, ISaGRAF may display the Property value is not valid message. Anomaly first identified in ISaGRAF version 6.6. [Rockwell TFS 42479]  
To work around this issue, close and re-open the project to update the dependency path.
- For SFC and IEC 61499, elements or files may be missing when opening projects from the version source control repository. Anomaly first identified in ISaGRAF version 6.2. [Rockwell TFS 13338/33850]  
There is no workaround.
- Initial values are not supported for Inputs of user-defined function blocks programmed in SFC. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 65515]  
To work around this issue, use LD, ST, FBD user-defined function blocks.
- When updating a solution or resource from an exchange file or from a repository, the variables are missing from the variable groups. Anomaly first identified in ISaGRAF version 6.3.2. [Rockwell TFS 24302]  
There is no workaround.
- When the compiler is unable to produce TIC code for FBD networks, the error list displays a warning message stating that the element is part of a tree not producing any code.  
To work around this issue and enable the production of TIC code, modify the network:
  - For rungs starting with a vertical bar, place a contact between the left power rail and the vertical bar. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 17814]
- Resolving the logic of FBD POUs with a manual execution order may require additional kernel execution cycles compared to the automatic execution. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 23702]  
There is no workaround.
- For variables using library-defined structure types with initial values, build errors occur after modifying the data types of the structure members since the initial values of these structure members are not reset after performing the modifications. Anomaly first identified in ISaGRAF

version 6.5. [Rockwell TFS 38311]

To work around this issue, remove the incorrect initial values after modifying the data types of structure members by changing the data type of the variable to any other type and then back to the original data type.

- When downloading a new IEC application where the virtual addresses and sizes of retained variables remain the same, previously retained values for such variables may be reused. Anomaly first identified in ISaGRAF version 6.3.2. [Rockwell TFS 44581]  
To work around this issue, avoid downloading multiple applications with the same name and virtual addresses for retained variables.
- I/O variable values are not updated when the I/O Device window is docked. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 23479]  
To work around this issue, force a refresh in the window by clicking on another I/O device instance.
- When opening an FBD POU while monitoring an application, tooltips display incorrectly with the `__MO_` prefix. Anomaly first identified in ISaGRAF version 6.2. [Rockwell TFS 12990]  
There is no workaround.
- The power flow debugging coloring displays incorrectly for rejected items. Rejected items are usually variables for which ISaGRAF is unable to resolve the access path. Rejected items appear in the Output window. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 40366]  
To work around this issue, chunk the access path for such variables using intermediary variables until producing the expected debugging behavior.
- When attempting to rename an IEC 61499 program to the same name as another existing program, an incorrect error message appears. Anomaly first identified in ISaGRAF version 6.2.2. [Rockwell TFS 51931]  
To work around this issue, use unique names.
- The function or function block dictionary displays internal and hidden structures from the .tdb file. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 54287]  
There is no workaround.
- Forcing a value on a wired structure output member that is locked overwrites only the first member of the structure. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 64548]  
There is no workaround.
- When monitoring multiple projects in a solution, only one project remains monitored after a few hours. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 65799]  
To work around this issue, specify the project that requires monitoring by right-clicking the project in Solution Explorer, and then selecting Set as StartUp Project.

### CAM 3

- When opening a project containing ISaVIEW documents located directly under a device node, POUs are hidden for devices with names other than the default naming such as "Device1". Anomaly first identified in ISaGRAF version 6.4.1. [Rockwell TFS 43385]

To work around this issue, perform either of these steps to ensure the complete display of elements in the Solution Explorer.

- Rename the devices to use the default naming, then close and reopen the project.
  - Place the ISaVIEW documents under POUs rather than under the device node.
- Passing a MESSAGE type variable as input for a REAL standard operator may cause a runtime fault. Anomaly first identified in ISaGRAF version 6.6. [Rockwell TFS 40295]  
To work around this issue, for the REAL operator, use any data type other than MESSAGE.
- For SFC steps and transitions, the renumbering feature applies the Sx and Tx naming convention used for CAM 5 SFC. Anomaly first identified in ISaGRAF version 6.3. [Rockwell TFS 38136]  
There is no workaround.
- When the data value for defined words exceeds the possible value range, the compiler may not specify an out-of-range error. Anomaly first identified in ISaGRAF version 6.4. [Rockwell TFS 18134]  
There is no workaround.
- The compiler optimization options produce incorrect TIC code. Anomaly first identified in ISaGRAF version 6.3. [Rockwell TFS 8311]  
To work around this issue, avoid applying these options.
- When importing variables for a function, an extra variable named 'NewVariable' is also added. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 38310]  
To work around this issue, delete the extra 'NewVariable' variable.
- An SFC program in the project may cause an incorrect program execution order. Anomaly first identified in ISaGRAF version 6.5. [Rockwell TFS 64534]  
To work around this issue, place SFC programs before ST, LD, and FBD programs in the Programs node in Solution Explorer.

### Additional Information (6.6.8)

For a list of every item addressed, see the file **C:\Program Files (x86)\Schneider Electric\SCADAPack Workbench\SCADAPack Workbench\Release Notes.html** installed with SCADAPack Workbench.

## SCADAPack Workbench 6.5.0 Release Notes

---

### Application Version

The SCADAPack Workbench application version is 6.5.0 (build 6.5.2146).

### Firmware Versions

- The latest SCADAPack firmware at the time of release is:
  - 1.75 for SCADAPack 314, SCADAPack 330, SCADAPack 334, SCADAPack 350, and SCADAPack 357 controllers
  - 1.63 for SCADAPack 4203 controllers
  - 2.23 for SCADAPack 32 and SCADAPack 32P controllers
  - 2.50 for SCADAPack 100 controllers

- 1.75 for NOCT60
- The latest SCADAPack E firmware at the time of release is 8.13.1 for SCADAPack E remote Programmable Automation Controllers (rPACs) and Remote Terminal Units (RTUs).

## New Features and Enhancements (6.5.0)

- Windows 10 (32-bit and 64-bit) support.
- SCADAPack Target 3 supports Sequential Function Chart (SFC) Programmable Organization Units (POUs) with some limitations:
  - Monitoring is not available while in simulation or running mode.
  - SFC macro steps (macro beginning steps, macro steps, and macro ending steps) are not supported.
- A Diagnostic view provides real-time statistical information about Target 3 and Target 5 applications.
- SCADAPack ES/ER templates for firmware versions 8.12.5+ include 8 new function blocks:
  - MODBUS\_SETUP\_RD\_BOOL
  - MODBUS\_SETUP\_RD\_REAL
  - MODBUS\_SETUP\_RD\_UDINT
  - MODBUS\_SETUP\_RD\_UINT
  - MODBUS\_SETUP\_WR\_BOOL
  - MODBUS\_SETUP\_WR\_REAL
  - MODBUS\_SETUP\_WR\_UDINT
  - MODBUS\_SETUP\_WR\_UINT
- SCADAPack sp350v1 and sp357v1 templates have been created for Target 3 projects that provide default I/O for 5 V/20 mA boards.

## Improvements (6.5.0)

- Migration to the Microsoft Visual Studio 2013 isolated shell:
  - The Solution Explorer provides new capabilities, including:
    - Searching the contents of the tree structure.
    - Collapsing and expanding tree structure views.
    - Scoping a specific element of the tree structure.
    - Passing from the default tree structure view to the previous or next view.
- The LD language editor includes the following improvements:
  - While dragging rungs, blocks, coils, contacts, jumps, returns, and branches, the language editor displays the possible drop points.
  - While debugging, the Ctrl-T keyboard shortcut toggles the Boolean logical value of a selected contact, coil, or block input.
  - Improved ability to select rungs using Control and Shift keys with a left-mouse click.
  - Improved keyboard navigation using the arrow keys.
- The Cross References Browser includes the following improvements:
  - Searches for Target 3 cross references.
  - Improved filtering options.

- Improved visibility of results including highlighting variable, block, or defined word search results and displaying locations for cross references.

## Functional Changes (6.5.0)

- When installing SCADAPack Workbench 6.5.0 on a computer that was running a previously licensed version, a message states that the free version is running. This means you need to activate the SCADAPack Workbench 6.5.0 license. To obtain new license registration keys, contact Schneider Electric customer support at [ordersTRSS@schneider-electric.com](mailto:ordersTRSS@schneider-electric.com).
- When installing SCADAPack Workbench 6.5.0, the new communication settings defined in C:\ProgramData\Schneider Electric\6.5\Schneider Electric Gateway\OpcConfig.xml file are applied to SCADAPack Workbench. If you were running a previous version of SCADAPack Workbench and now experience communication issues, revert the IxTimeoutMultiFactor, ConnectRetryTimeInterval, and ConnectNoResponseTimeOut values in the OpcConfig.xml file to their previous values.
- For POU's created in SCADAPack Workbench 6.3.0 or earlier, you need to open a local copy of the POU, make a change, then save the POU to ensure the XML files are updated to the current SCADAPack Workbench version.
- SCADAPack Workbench cannot load projects with an invalid name. Valid project names begin with letters followed by letters, digits, and single underscore characters. Names cannot be reserved words or data types (defined words or arrays).

## Technical Notes (6.5.0)

- The following issues are corrected by installing the Visual Studio 2013 Update 5 available at <https://www.microsoft.com/en-ca/download/details.aspx?id=48129>
  - The incomplete display of some or all toolbox items upon resetting for FBD, LD, SFC, or ST programming languages.
  - For the online help, hypertext links jumping to the top of the page rather than in the specific paragraphs within the same page.
  - The inability to change menu items from uppercase to mixed case.
  - The wrongful inclusion of the non-implemented "Order Help on DVD" menu item from the Help menu.
- When performing searches from the Solution Explorer to locate specific items within the tree structure, searches are case-insensitive for lowercase text in the search field. However, searches become case-sensitive upon entering uppercase text in the field. Microsoft states this behavior is as designed: <https://connect.microsoft.com/VisualStudio/feedback/details/1078288/solution-explorer-search-filter-is-case-sensitive-it-should-be-case-insensitive>
- When SCADAPack Workbench displays a message stating that the ACP has encountered a problem, please take the time to generate a report to help us improve the quality of our product. When generating a report, you can choose to capture and attach a screenshot. Upon generation, a dialog box indicates the location and name of the report where you can choose to send the file to our technical support team at [supportTRSS@schneider-electric.com](mailto:supportTRSS@schneider-electric.com). For such problems, make sure to

close SCADAPack Workbench without saving changes to your project and restart the software to avoid corrupting files.

## Fixed Issues (6.5.0)

### Target 3 and Target 5

- **Issue:** A defined word name could exceed the 252 maximum character length, causing unexpected behavior in SCADAPack Workbench.  
**Fix:** The defined word name is properly validated to prevent unexpected behavior.  
**Engineering Reference:** IES6-1087
- **Issue:** ISaVIEW projects could not be exported as templates using the “Export as Template” feature.  
**Fix:** The “Export as Template” functionality for ISaVIEW projects has been corrected.  
**Engineering Reference:** IES6-1094
- **Issue:** Focusing on an ISaVIEW window during a download caused unexpected behavior in SCADAPack Workbench.  
**Fix:** Display and focus issues on ISaVIEW pages have been corrected.  
**Engineering Reference:** IES6-1097
- **Issue:** The Document Viewer sometimes caused unexpected behavior in SCADAPack Workbench.  
**Fix:** The Document Viewer is now more stable and no longer causes SCADAPack Workbench to crash if its position is changed.  
**Engineering Reference:** IES6-1099
- **Issue:** Tag names on the LD canvas were truncated in a way that made them difficult to read.  
**Fix:** Long tag names are truncated in the middle using "...", and a tooltip is provided to indicate the full tag name when hovering over a variable.  
**Engineering Reference:** IES6-1170

### Target 5 Only

- **Issue:** The controller status was reported as "not alive" on the first download attempt if a program was already running in the RTU.  
**Fix:** The Target 5 download mechanism has been improved and no longer reports “not alive” on download if a program already exists and is running.  
**Engineering Reference:** IES6-837
- **Issue:** SCADAPack Workbench becomes unresponsive after attempting to access a variable after communication is lost.  
**Fix:** Target 5 communication is now more robust to help prevent SCADAPack Workbench from becoming unresponsive.  
**Engineering Reference:** IES6-941

- **Issue:** The Modbus Master function block documentation was incomplete.  
**Fix:** The Modbus Master function block documentation has been improved.  
**Engineering Reference:** IES6-1150, IES6-1178
- **Issue:** Documentation did not state that the Windows Runtime Modules are not supported on SCADAPack firmware.  
**Fix:** The *Migrating ISaGRAF 3 Workbench Projects to SCADAPack Workbench* documentation now includes a more detailed list of unsupported features.  
**Engineering Reference:** IES6-1175

### Target 3 Only

- **Issue:** The "IsRetained" checkbox did not properly display in the variable table, although the value was correct.  
**Fix:** The control window is now refreshed as expected.  
**Engineering Reference:** IES6-844
- **Issue:** An "Application stopped" message was displayed in the output window after a download, even though the application was running in the device.  
**Fix:** The Output window is now cleared after the download is complete.  
**Engineering Reference:** IES6-846
- **Issue:** The Cross Reference browser did not find all references of the object.  
**Fix:** The Cross Reference browser now retrieves all expected results.  
**Engineering Reference:** IES6-944
- **Issue:** Users could not enter simulation mode if SCADAPack Workbench was opened via an \*.acfproj or \*.isasIn file in Windows Explorer.  
**Fix:** The working directory for the SCADAPack Workbench project is correctly defined and projects that are opened from Windows Explorer can be debugged using the Simulator.  
**Engineering Reference:** IES6-1102
- **Issue:** The Cycle Timing value was not reset when a new debug instance was initialized.  
**Fix:** The Cycle Timing value is cleared and applied as expected.  
**Engineering Reference:** IES6-1124
- **Issue:** Documentation for Modbus Setup blocks was incorrect.  
**Fix:** The documentation has been improved.  
**Engineering Reference:** IES6-1143
- **Issue:** Variable instances were not recognized in the Spy List when adding the "Add to Spylist" option from the context menu.



**Fix:** The Spy List functionality has been improved.

**Engineering Reference:** IES6-1169

- **Issue:** Target 3 projects were sometimes automatically rebuilt when attempting to enter debug mode, causing a version mismatch between the rPAC and SCADAPack Workbench.

**Fix:** Projects are no longer automatically rebuilt when entering a debug session.

**Engineering Reference:** IES6-1190

For a list of every item addressed, see the file AcpResolvedIssues.txt in C:\Program Files (x86)\Schneider Electric\SCADAPack Workbench\SCADAPack Workbench.

## Known Issues/Known Customer Difficulties (6.5.0)

### Target 3 and Target 5

- **Issue:** Attempting to run multiple instances of SCADAPack Workbench may cause unexpected behavior.

**Workaround:** Run a single instance of SCADAPack Workbench.

**Engineering Reference:** N/A

- **Issue:** The Instruction List (IL) programming language is not implemented. You cannot open Program Organization Units (POUs) written in this language.

**Workaround:** N/A

**Engineering Reference:** N/A

- **Issue:** When creating elements, names with more than 32 characters can exceed the maximum path name length supported by Microsoft Windows operating systems.

**Workaround:** Avoid using names with more than 32 characters.

**Engineering Reference:** N/A

- **Issue:** The “Find and Replace” feature’s “Find Next” and “Replace” commands are available only within the context of the ‘Current Document’ for POUs.

**Workaround:** Perform Search and Replace for a POU by clicking Ctrl+F, then setting the ‘Look In’ field to ‘Current Document’ and using only the “Find Next” or “Replace” commands.

**Engineering Reference:** ISE6-1153

- **Issue:** Toolbox icons are not displayed properly when using a Windows display setting other than 100%.

**Workaround:** Use only Windows display settings of 100% when running SCADAPack Workbench.

**Engineering Reference:** N/A

- **Issue:** You cannot drag POU body elements between different programming language containers. Trying to do so can cause unexpected behavior in SCADAPack Workbench.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** The dictionary displays an incorrect lock status for variables.  
**Workaround:** Use the Locked Variables viewer to see the correct lock status for variables.  
**Engineering Reference:** N/A
- **Issue:** The Block Library or Variable Selector is not automatically displayed for Ladder Diagram (LD) POUs when you double-click on coils and contacts in the Toolbox.  
**Workaround:** To display the Block Library or Variable Selector, insert coils and contacts in the Toolbox, then double-click on them.  
**Engineering Reference:** N/A
- **Issue:** Using the Document Overview for a Function Block Diagram (FBD) POU can cause unexpected behavior in SCADAPack Workbench.  
**Workaround:** N/A  
**Engineering Reference:** ISE6-1099
- **Issue:** When using the Documentation Generator, the generated document is dependent on the zoom level of the open FBD POU.  
**Workaround:** Close all POUs before generating the document.  
**Engineering Reference:** N/A
- **Issue:** When resetting the toolbox for FBD, LD, SFC, or ST programming languages, the icons for some or all elements may not display correctly.  
**Workaround:** Close and reopen SCADAPack Workbench.  
**Engineering Reference:** N/A
- **Issue:** In the Customize dialog box for menu bar, toolbar, and context menu items, avoid applying the "Reset All" command since this operation may cause unexpected behavior.  
**Workaround:** To remove the effects of the "Reset All" command, you can reset all environment settings to their defaults by choosing Tools > Import and Export Settings then selecting the "Reset all settings" option.  
**Engineering Reference:** N/A
- **Issue:** Real values are displayed as integers in ISaVIEW text variables.  
**Workaround:** N/A  
**Engineering Reference:** IES6-1114

- **Issue:** Opening the Diagnostics window while offline may cause SCADAPack Workbench to become temporarily unresponsive.  
**Workaround:** Avoid opening the Diagnostics window when not actively connected to a device.  
**Engineering Reference:** IES6-1235

#### Target 5 Only

- **Issue:** If you download a new IEC 61131-3 application with virtual addresses and retained variable sizes that are the same as an existing application, the existing values for these variables may be reused in the new application.  
**Workaround:** Avoid downloading multiple applications that have the same names and sizes for retained variables.  
**Engineering Reference:** N/A
- **Issue:** I/O variable values are not updated when the I/O Device window is docked.  
**Workaround:** To view updated values, click on another I/O Device instance to force the window to refresh.  
**Engineering Reference:** N/A
- **Issue:** A virtual address overlap occurs if you delete an IEC 61131-3 function with an anonymous array as a complex parameter and the function uses the complex parameter (usually the case).  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** Copying programs with wired array variables can cause unexpected behavior in SCADAPack Workbench.  
**Workaround:** Delete the array variables in the copied program.  
**Engineering Reference:** N/A
- **Issue:** Copying FBD POUs from programs to function blocks can cause unexpected behavior in SCADAPack Workbench.  
**Workaround:** Copy subsets of the POU body between programs and function blocks.  
**Engineering Reference:** N/A
- **Issue:** You need to unwire wired variables before modifying the dimension.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** Running an application that contains non-instantiated Sequential Function Chart (SFC) function blocks with SFC child blocks can cause unexpected behavior on the target.  
**Workaround:** N/A  
**Engineering Reference:** N/A

- Issue:** Since the release of Target 5, the behavior of SFC steps with non-stored (N) action qualifiers has been modified to comply with the IEC 61131-3 standard. SFC steps are now executed when they are activated and when they are deactivated.

**Workaround:** If the action only needs to be executed once, replace the N qualifier with a P0 or a P1 qualifier in the action's properties in applications that have non-stored (N) action qualifiers in SFC Steps.

**Engineering Reference:** N/A
- Issue:** If you open an FBD POU while monitoring an application, tooltips are incorrectly displayed with the \_\_MO\_ prefix.

**Workaround:** N/A

**Engineering Reference:** N/A
- Issue:** You cannot monitor the values of arrays that have a variable as an index.

**Workaround:** N/A

**Engineering Reference:** N/A
- Issue:** When using ISaVIEW documents, you cannot access individual integer bits.

**Workaround:** N/A

**Engineering Reference:** N/A
- Issue:** ISaGRAF eXchange Layer (IXL) communication with a target may be unsuccessful.

**Workaround:** Try the following:

  - Start simulation from the toolbar to test communications with the simulator.
  - Use the Windows Add/Remove Programs feature to verify that the "OPC Core components redistributable" item is installed.
  - If the SCADAPack Workbench runtime is installed on a quad-core computer, set the CPU affinity to one core.

**Engineering Reference:** N/A
- Issue:** Function block input and output labels are displayed using pin ids instead of full names.

**Workaround:** View the full name of the input/output in the Block Selector view.

**Engineering Reference:** ISE6-692
- Issue:** When attempting to debug or simulate a project with a number of variables that exceed the available memory, the output window displays the "OPC server is unable to load project..." message and the "OutOfMemoryException: calling OPC Server shutdown" error message. The debugging or simulation process terminates and SCADAPack Workbench returns to project editing mode.

**Workaround:** N/A

**Engineering Reference:** N/A

- Issue:** When updating a solution or resource from an exchange file, the variables are missing from the variable groups.

**Workaround:** N/A

**Engineering Reference:** N/A
- Issue:** When editing the properties of a POU body, you need to click elsewhere in the editor workspace before proceeding.

**Workaround:** N/A

**Engineering Reference:** N/A
- Issue:** When the compiler is unable to produce TIC code for FBD networks, the error list displays a warning message stating that the element is part of a tree not producing any code.

**Workaround:** To enable the production of TIC code, you need to modify the network:

  - For rungs starting with a vertical bar, place a contact to the left on the rung.
  - For networks having a loop, replace the loop with variables.

**Engineering Reference:** N/A
- Issue:** Loops in FBD networks may produce unexpected execution order results.

**Workaround:** When placing loops in FBD networks, verify that the execution order follows your intended results.

**Engineering Reference:** N/A
- Issue:** Resolving the logic of FBD POUs with a manual execution order may require additional kernel execution cycles compared to using automatic execution.

**Workaround:** N/A

**Engineering Reference:** N/A
- Issue:** For variables using library-defined structure types with initial values, build errors occur after modifying the data types of the structure members because the initial values of these structure members are not reset after performing the modifications.

**Workaround:** To remove the incorrect initial values after modifying the data types of structure members, change the data type of the variable to any other type, then back to the original data type.

**Engineering Reference:** N/A
- Issue:** Starting debugging with closed FBD POUs containing user-defined functions causes the error icon to be displayed on the block either when the POU is opened during simulation or when simulation is stopped.

**Workaround:** Open all FBD POUs containing user-defined functions before debugging.

**Engineering Reference:** N/A

- **Issue:** When using the document generator on a SFC program, embedded transitions where ST or LD are used do not get generated and are therefore not documented.  
**Workaround:** N/A  
**Engineering Reference:** ISE6-1201

### Target 3 Only

- **Issue:** Recursive folders may be created when importing ISaGRAF 3 Workbench projects into SCADAPack Workbench.  
**Workaround:**
  - Choosing the folder where the \*.hie file is stored can cause unexpected behavior in SCADAPack Workbench. Choose a different folder.
  - ISaGRAF 3 Workbench project folder names with more than eight characters can cause unexpected behavior in SCADAPack Workbench. Before importing, shorten the ISaGRAF 3 Workbench folder name if necessary.

**Engineering Reference:** ISE6-1033

- **Issue:** Device names with more than 8 characters cause unknown compilation events.  
**Workaround:** Avoid using device names with more than 8 characters.  
**Engineering Reference:** N/A
- **Issue:** After running a project with a POU, then deleting the POU, SCADAPack Workbench may not prompt you to rebuild the project before restarting simulation.  
**Workaround:** N/A  
**Engineering Reference:** N/A

- **Issue:** The values of unused variables are displayed as Offline.  
**Workaround:** N/A  
**Engineering Reference:** ISE6-963

- **Issue:** The compiler optimization options produce unstable results.  
**Workaround:** Avoid applying these options.  
**Engineering Reference:** N/A

- **Issue:** Importing variables removes all I/O wiring connections.  
**Workaround:** Rewire variables after importing.  
**Engineering Reference:** ISE6-1013

- **Issue:** Simulating Target 3 projects requires administrator privileges.  
**Workaround:** Run SCADAPack Workbench with administrator privileges:
  1. Locate the SCADAPack Workbench application and right-click on it.
  2. Choose Run as administrator.

**Engineering Reference:** N/A

- **Issue:** The Cross References Browser does not display cross references for Target 3 SFC POUs.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** Support for imported Instruction List (IL) programming in SFC may be incomplete. This programming is displayed in steps with header and footer delimiters as in ISaGRAF 3.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** After modifying an SFC program with SFC children, the project needs to be cleaned.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** When copying an SFC POU that calls SFC children, the copied POU displays correctly in the Solution Explorer. However, the SFC actions calling the children are not copied; these actions are empty.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** For SFC steps and transitions, the renumbering feature applies the Sx and Tx naming convention used for Target 5 SFC  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** When the data value for defined words exceeds the possible value range, the compiler may not specify an out-of-range error.  
**Workaround:** N/A  
**Engineering Reference:** N/A
- **Issue:** Unloading then reloading a Target 3 library project is not recommended as this may cause unexpected behavior in SCADAPack Workbench.  
**Workaround:** Unload the library project, close the solution, re-open the solution, then reload the library project.  
**Engineering Reference:** N/A
- **Issue:** When importing variables for a function, an extra variable named "NewVariable" is added.  
**Workaround:** Delete the extra NewVariable variable.  
**Engineering Reference:** N/A
- **Issue:** The "Execution Order" feature is not implemented for Target 3 FBD POUs.

**Workaround:** N/A

**Engineering Reference:** IES6-1141

- **Issue:** Local defined words cannot be selected from the variable selector in a POU.  
**Workaround:** Do not use the Variable Selector popup that is accessed by double-clicking on a variable. Instead, use the quick access variable dropdown selector to assign a local defined word to a variable.  
**Engineering Reference:** IES6-1155
- **Issue:** Entering a negative “Cycle Timing” value causes unexpected behavior.  
**Workaround:** Do not enter negative values in the “Cycle Timing” control.  
**Engineering Reference:** IES6-1122
- **Issue:** Downloading a project while the I/O Wiring window is active may cause unexpected behavior in SCADAPack Workbench.  
**Workaround:** Close the I/O Wiring window before downloading a project.  
**Engineering Reference:** IES6-1129
- **Issue:** Updating the communication settings after renaming a device may cause unexpected behavior.  
**Workaround:** Avoid opening the Diagnostics window when not actively connected to a device.  
**Engineering Reference:** IES6-1194
- **Issue:** Variables may appear to retain their initial value after a clean or a rebuild.  
**Workaround:** Close the variable (VAR) window and re-open it to force the user interface to refresh.  
**Engineering Reference:** IES6-867
- **Issue:** Cannot start debugging for a Target 3 program in the RTU.  
**Workaround:** Erase the Target 3 program in the RTU, re-download it to the device, then try to start debugging again. If that doesn't work, create a new SCADAPack Workbench project, clean the solution, build it, download it to the RTU, then try to start debugging again.  
**Engineering Reference:** IES6-1242



# SCADAPack Workbench 6.4.1 Release Notes

---

## Application Version

The SCADAPack Workbench application version is 6.4.1 (build 1.4.1233).

## Firmware Versions

- The latest SCADAPack firmware at the time of release is:
  - 1.75 for SCADAPack 314, SCADAPack 330, SCADAPack 334, SCADAPack 350, and SCADAPack 357 controllers
  - 1.63 for SCADAPack 4203 controllers
  - 2.23 for SCADAPack 32 and SCADAPack 32P controllers
  - 2.50 for SCADAPack 100 controllers
  - 1.75 for NOCT60
- The latest SCADAPack E firmware at the time of release is 8.12.4 for SCADAPack E remote Programmable Automation Controllers (rPACs) and Remote Terminal Units (RTUs).

## New Features and Enhancements (6.4.1)

These features are included:

- SCADAPack 500 E templates for firmware versions 8.12.4+ include 3 new HART function blocks: HART\_CMD, HART\_DEVICE\_SCAN and HART\_MTL4851\_CTRL.

## Improvements (6.4.1)

These improvements are included:

- Improved installation feedback and logging.

## Fixed Issues (6.4.1)

These issues are fixed:

- **Issue:** Projects are automatically rebuilt before downloading, which may cause communication timeouts.  
**Fix:** Projects are no longer rebuilt before downloading or entering a debug session.  
**Engineering Reference:** ISE6-1146

## Known Issues/Known Customer Difficulties (6.4.1)

These issues are known:

- **Issue:** Visual Studio Service Pack 1 may require manual installation.  
**Workaround:** Visual Studio Service Pack 1 can be installed from the prerequisites folder on the DVD (Prerequisites\VS2010ISO\SP1\setup.exe), or it can be downloaded from the Microsoft website.  
**Engineering Reference:** ISE6-1142

# SCADAPack Workbench 6.4.0 Release Notes

---

## Application Version

The SCADAPack Workbench application version is 6.4.0 (build 1.4.1233).

## Firmware Versions

- The latest SCADAPack firmware at the time of release is:
  - 1.75 for SCADAPack 314, SCADAPack 330, SCADAPack 334, SCADAPack 350, and SCADAPack 357 controllers
  - 1.63 for SCADAPack 4203 controllers
  - 2.23 for SCADAPack 32 and SCADAPack 32P controllers
  - 2.50 for SCADAPack 100 controllers
  - 1.75 for NOCT60
- The latest SCADAPack E firmware at the time of release is 8.12.2 for SCADAPack E remote Programmable Automation Controllers (rPACs) and Remote Terminal Units (RTUs)

## New Features and Enhancements (6.4.0)

These features are now supported:

- Windows 8 and Windows 8.1 operating systems
- Foxboro NOCT (model NOCT60) Target 3 project configurations
- Target 3 document generation

## Improvements (6.4.0)

These improvements are included:

- Improved stability and robustness of the SCADAPack Workbench installer
- Improved stability and robustness of the Online Change feature
- Improved functionality of the Document Generator
- Improved robustness of Target 5 Application Package
- Added support for the Delete key in Function Block Diagram (FBD) comment blocks
- Improved legibility of text in variable box in FBD programs
- Improved contrast between text and background colors of FBD and Ladder Diagram (LD) elements
- Simplified documentation for Target 3 library dependency referencing
- Corrected various typos in the documentation and SCADAPack templates

## Corrections (6.4.0)

These items are fixed:

- Item: I/O Wiring offset was not respected when importing a Target 3 project from ISaGRAF 3 Workbench.  
Fix: Wiring offsets are now retained when importing a Target 3 project from ISaGRAF 3 Workbench into SCADAPack Workbench.  
Engineering Reference: ISE6-1032

- Item: Function Block programs did not clearly indicate power flow in debug mode.  
 Fix: Power flow is now properly indicated in Function Block programs when in debug mode.  
 Engineering Reference: ISE6-706
- Item: Users could not enter a REAL constant in a variable box.  
 Fix: Corrected numeric format validation inconsistencies in the variable box element.  
 Engineering Reference: ISE6-974
- Item: The option to add a Target 5 dependency was missing from SCADAPack E templates.  
 Fix: Added the "Add Dependency" option to the Solution Explorer.  
 Engineering Reference: ISE6-981
- Item: A prompt indicated the project had to be rebuilt when attempting to download the project to a controller. Pressing Cancel stopped the download; pressing OK could result in a communication timeout.  
 Fix: Removed the prompt so the compiled project can be downloaded without interruption.  
 Engineering Reference: ISE6-432
- Item: The Device Selector dialog box sometimes hid the OK and Close buttons.  
 Fix: Adjusted the button position on the Device Selector dialog box.  
 Engineering Reference: ISE6-662
- Item: Mismatched data types between variables and function blocks caused power lines to turn red in Function Block Diagram (FBD) programs.  
 Fix: Fixed data type inconsistencies between variables and function blocks.  
 Engineering Reference: ISE6-895
- Item: Local variables contained within a single ISaGRAF 3 Workbench project each needed a unique name to be imported into SCADAPack Workbench regardless of their scope.  
 Fix: Local variables are now validated against name and scope when they are imported into SCADAPack Workbench.  
 Engineering Reference: ISE6-943
- Item: Variable formats were validated differently when importing projects and when exporting projects.  
 Fix: Import and export validation is now consistent.  
 Engineering Reference: ISE6-854
- Item: The "Launch SCADAPack Configurator" menu option disappeared after adding a custom dependency to a SCADAPack Target 3 project.  
 Fix: The "Launch SCADAPack Configurator" menu option is now available for valid SCADAPack solutions.  
 Engineering Reference: ISE6-1006

- Item: Refreshing a function block reverted changes without saving them.  
Fix: Function block modifications are now retained as expected when a change is made.  
Engineering Reference: ISE6-1011
- Item: Target 5 projects had to be downloaded one resource at a time.  
Fix: Changed communication timeouts so two resources can be downloaded at the same time.  
Engineering Reference: ISE6-1015
- Item: An unexpected OPC event occurred when downloading Target 5 projects.  
Fix: Changed the SCADAPack Workbench installer so OPC components are installed as expected.  
Engineering Reference: ISE6-1056
- Item: I/O devices did not show new I/O variables immediately after they were added.  
Fix: Changed the user interface display refresh interval so I/O variables are displayed immediately after they are added.  
Engineering Reference: ISE6-999
- Item: The Deployment View was not updated after a device was deleted.  
Fix: Changed the user interface display refresh interval so the Deployment View is updated when changes are made.  
Engineering Reference: ISE6-638
- Item: Channel variables were still shown after the I/O device was deleted.  
Fix: Changed the user interface display refresh interval so channel variables are no longer shown after the I/O device is deleted.  
Engineering Reference: ISE6-678
- Item: Target 3 Structured Text (ST) programs could not be edited after they were downloaded.  
Fix: Changed the user interface display refresh interval so ST programs can be edited after they are downloaded.  
Engineering Reference: ISE6-848

For a list of every item addressed, see the file AcpResolvedIssues.txt in C:\Program Files (x86)\Schneider Electric\SCADAPack Workbench\SCADAPack Workbench.

## Items to be Aware Of (6.4.0)

### Target 3 and Target 5

- Item: The Instruction List (IL) and Sequential Function Chart (SFC) programming languages are not implemented. You cannot open Program Organization Units (POUs) written in these languages.  
Workaround: N/A  
Engineering Reference: N/A
- Item: You cannot drag POU body elements between different programming language containers. Trying to do so can cause unexpected behavior in SCADAPack Workbench.  
Workaround: N/A  
Engineering Reference: N/A
- Item: The dictionary displays an incorrect lock status for variables.  
Workaround: Use the Locked Variables viewer to see the correct lock status for variables.  
Engineering Reference: N/A
- Item: The "Save Solution/Project as" feature is no longer available.  
Workaround: Use Windows Explorer to make a copy of the project, then rename it.  
Engineering Reference: ISE6-972, IES6-1043
- Item: The Block Library or variable selector is not automatically displayed for Ladder Diagram (LD) POUs when you double-click on coils and contacts in the Toolbox.  
Workaround: To display the Block Library or variable selector, insert coils and contacts in the Toolbox, then double-click on them.  
Engineering Reference: N/A
- Item: Using the Document Overview for a Function Block Diagram (FBD) POU can cause unexpected behavior in SCADAPack Workbench.  
Workaround: N/A  
Engineering Reference: ISE6-1099
- Item: Unable to enter simulation mode if SCADAPack Workbench was opened via an \*.acfproj or \*.isasln file in Windows Explorer.  
Workaround: Do not open project or solution files directly from Windows Explorer. Open SCADAPack Workbench, then use the File > Open command to open project and solution files.  
Engineering Reference: ISE6-1102
- Item: In the ISaVIEW context menu, the Delete and Rename options can be selected even when they are invalid options.  
Workaround: N/A  
Engineering Reference: ISE6-1093

- Item: The ISaVIEW Export as Template context menu option may generate an exception.  
Workaround: N/A  
Engineering Reference: ISE6-1094
- Item: The Add > ISaVIEW from Template context menu option may not find the path to the template.  
Workaround: N/A  
Engineering Reference: ISE6-1095
- Item: Selecting the ISaVIEW page while an application is downloading may cause the SCADAPack Workbench application to close.  
Workaround: N/A  
Engineering Reference: ISE6-1097

### Target 5 Only

- Item: After downloading SCADAPack Workbench projects with two resources, communications with the rPAC or RTU may be lost.  
Workaround: Restart the rPAC or RTU.  
Engineering Reference: ISE6-1085
- Item: If you download a new IEC application with virtual addresses and retained variable sizes that are the same as an existing application, the existing values for these variables may be reused in the new application.  
Workaround: Avoid downloading multiple applications that have the same names and sizes for retained variables.  
Engineering Reference: N/A
- Item: I/O variable values are not updated when the I/O Device window is docked.  
Workaround: To view updated values, click on another I/O Device instance to force the window to refresh.  
Engineering Reference: N/A
- Item: A virtual address overlap occurs if you delete an IEC function with an anonymous array as a complex parameter and the function uses the complex parameter (usually the case).  
Workaround: N/A  
Engineering Reference: N/A
- Item: Copying programs with wired array variables can cause unexpected behavior in SCADAPack Workbench.  
Workaround: Delete the array variables in the copied program.  
Engineering Reference: N/A

- Item: Copying FBD POUs from programs to function blocks can cause unexpected behavior in SCADAPack Workbench.  
Workaround: Copy subsets of the POU body between programs and function blocks.  
Engineering Reference: N/A
- Item: You need to unwire wired variables before modifying the dimension.  
Workaround: N/A  
Engineering Reference: N/A
- Item: Running an application that contains non-instantiated Sequential Function Chart (SFC) function blocks with SFC child blocks can cause unexpected behavior on the target.  
Workaround: N/A  
Engineering Reference: N/A
- Item: Since the release of Target 5, the behavior of SFC steps with non-stored (N) action qualifiers has been modified to comply with the IEC 61131-3 standard. As a result, SFC steps are now executed when they are activated and when they are deactivated.  
Workaround: If the action only needs to be executed once, replace the N qualifier with a P0 or a P1 qualifier in the action's properties in applications that have non-stored (N) action qualifiers in SFC Steps.  
Engineering Reference: N/A
- Item: If you open an FBD POU while monitoring an application, tooltips are incorrectly displayed with the \_\_MO\_ prefix.  
Workaround: N/A  
Engineering Reference: N/A
- Item: You cannot monitor the values of arrays that have a variable as an index.  
Workaround: N/A  
Engineering Reference: N/A
- Item: When using ISaVIEW documents, you cannot access individual integer bits.  
Workaround: N/A  
Engineering Reference: N/A
- Item: ISaGRAF eXchange Layer (IXL) communication with a target may be unsuccessful.  
Workaround: Try the following:
  - Start simulation from the toolbar to test communications with the simulator.
  - Use the Windows Add/Remove Programs feature to verify that the "OPC Core components redistributable" item is installed.

- If the SCADAPack Workbench runtime is installed on a quad-core computer, set the CPU affinity to one core.

Engineering Reference: N/A

- Item: When creating elements, names with more than 32 characters may exceed the maximum path name length supported by Microsoft Windows operating systems.  
Workaround: Avoid using names with more than 32 characters.  
Engineering Reference: N/A
- Item: Function block input and output labels are displayed using pin ids instead of full names.  
Workaround: View the full name of the input/output in the Block Selector view.  
Engineering Reference: ISE6-692
- Item: The controller status may be reported as “not alive” on first download attempt.  
Workaround: Attempt to download the project again.  
Engineering Reference: ISE6-837

### Target 3 Only

- Item: Recursive folders may be created when importing ISaGRAF 3 Workbench projects into SCADAPack Workbench.
- Workaround:
  - Choosing the folder where the \*.hie file is stored can cause unexpected behavior in SCADAPack Workbench. Choose a different folder.
  - ISaGRAF 3 Workbench project folder names with more than eight characters can cause unexpected behavior in SCADAPack Workbench. Before importing, shorten the ISaGRAF 3 Workbench folder name if necessary.

Engineering Reference: ISE6-1033

- Item: Device names with more than eight characters cause unknown compilation events.  
Workaround: Avoid using device names of more than 8 characters.  
Engineering Reference: N/A
- Item: After running a project with a POU, then deleting this POU, SCADAPack Workbench may not prompt you to rebuild the project before restarting simulation.  
Workaround: N/A  
Engineering Reference: N/A
- Item: The values of unused variables are displayed as Offline.  
Workaround: N/A  
Engineering Reference: ISE6-963
- Item: The compiler optimization options produce unstable results.



Workaround: Avoid applying these options.

Engineering Reference: N/A

- Item: Importing variables removes all I/O wiring connections.

Workaround: Variables need to be rewired after importing.

Engineering Reference: ISE6-1013

- Simulating Target 3 projects requires administrator privileges.

Workaround: Run SCADAPack Workbench with administrator privileges:

1. In your computer's Start menu, locate the SCADAPack Workbench application and right-click on it.
2. Choose Run as administrator.

Engineering Reference: N/A